

: P M H



K I N T E K
5 0 0

	- 3 0 0 . 0 5 0 0
	4 4 0 C
	HRC60 HRC62
	1 0 1 3 1 5 2 0 3 0 4 0 mm
	4 0 mm (N)
	7 8 * 1 3 8 mm 9 0 * 1 3 8 mm L * * H
	3 0 0 W 2 2 0 V / 1 1 0 V
	9 k g

[M p a	5 0	1 0 0	3 0 0	4 0 0	6 0 0	8 0 0	1 0 0 0	1 2 0 0	1 5 0 0
8 T	0 . 2 5	0 . 5	1 . 5	2 . 0 1	3 . 0 1	4 . 0 2	5 . 0 2	6 . 0 3	7 . 5 3
1 0 T	0 . 3 9	0 . 7 8	2 . 3 5	3 . 1 4	4 . 7 1	6 . 2 8	7 . 8 5	9 . 4 2	1 1 . 7
1 2 T	0 . 5 6	1 . 1 3	3 . 3 9	4 . 5 2	6 . 7 8	9 . 0 4	1 1 . 3	1 3 . 5	1 6 . 9
1 3 T	0 . 6 6	1 . 3 2	3 . 9 8	5 . 3	7 . 9 6	1 0 . 6	1 3 . 2	1 5 . 9	1 9 . 9
1 5 T	0 . 8 8	1 . 7 6	5 . 3	7 . 0 6	1 0 . 6	1 4 . 1	1 7 . 6	2 1 . 2	2 6 . 5
2 0 T	1 . 5 7	3 . 1 4	9 . 4 2	1 2 . 5	1 8 . 8	2 5 . 1	3 1 . 4	3 7 . 6	4 7 . 1